



PURPOSE OF FLIGHT:

General flying exercises.

NATURE OF ACCIDENT:

Was carrying out general flying exercise when a rocker box exhaust cracked causing the engine to cut and lose revs. Was losing height rapidly so decided to make a forced landing.

CLASSIFICATION:

17. Forced landing.

SECONDARY OR CONTRIBUTORY FACTORS:

26. Engine trouble - no damage

TECHNICAL OFFICER'S REPORT:

Crack around #2 ~~exhaust~~ exhaust rocker box.

FB/AOP/ES/VAD/11/UOK/B ✓

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

10961

ACTION TAKEN:

NIL