

CASPIR Aircraft Accident Cards

Serial: 2796

Title: North American Harvard Mk.II serial:2796 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 2 aircraft on 1944-August-29. They are: Harvard II s/n FE818, Harvard II s/n 2796. This accident involved 3 people. Ball RGH, Mawalagedera PB, Millard P

Keywords: RAFHarvard II,2796,34 SFTS,34 Service Flying Training School,Drome Medicine Hat,1944-August-29,Ball,Mawalagedera,MillardRCAF L20

Created: 1944-08-29

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#2796>

PURPOSE OF FLIGHT:

Taxying.

TECHNICAL OFFICER'S REPORT:

MULT

MIL.

TCA/PCTL
TCA/XA

NATURE OF ACCIDENT:

A/C No. 2796 was being taxied along the perimeter track towards the take off point, when it struck the stbd. wing of No. 818, which was stationary

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

9. Collision.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Log Book Endorsed "Gross Carelessness."