

CASPIR Aircraft Accident Cards

Serial: AJ909

Title: North American Harvard Mk. II serial:AJ909 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1944-August-31. Harvard II s/n AJ909. This accident involved 1 person. Archer J

Keywords: RAFHarvard II,AJ909,34 SFTS,34 Service Flying Training School,Aerodrome,1944-August-31,ArcherRCAF L20

Created: 1944-08-31

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#AJ909>

ACCIDENT CLASSIFICATION

DATE **31-8-44** TIME **2205**

UNIT **34 S.F.T.S.
Medicine Hat**

COM. **4**

PLACE **M.A.**

H.Q. FILE **1300-AJ909**

A/C TYPE

HARVARD II

No.

AJ909

CRASH CAT.

"B"

S.E.

M.E.

DAY

NIGHT

PERSONNEL

RANK

NUMBER

DUTY

INJURIES

SIGNAL

ARCHER, J.

LAC 1588168

PP Uninj.

No.

DATE

D 14 (REVISED)

No.

CHECKED

#86

ENGINE

ENGINE NUMBER (S)

HOURS FLOWN BY PILOTS

Waap S3HI

11401/313682

INST.

NIGHT

ON TYPE

TOTAL

25

13

DUAL

SOLO

DUAL

SOLO

78

66

127

95

ACCIDENT CLASSIFICATION

TYPE OF A/C

TYPE OF UNIT


CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

- FORCED LANDING
- TAKING OFF
- LANDING
- FLIGHT
- STATIONARY
- FATAL
- INJ.
- INJURY



PURPOSE OF FLIGHT:

Solo night flying circuits and landings.

TECHNICAL OFFICER'S REPORT:

NIL

LS/PSS/USS ✓

NATURE OF ACCIDENT:

This a/c made a normal landing and then swung violently to the left resulting in damage to a/c.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

2. Swung.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

NIL