

ACCIDENT CLASSIFICATION

UNIT 15 S.F.T.S.
Claresholm

COM. 4

PLACE R.2 Champion

DATE 23-9-44 TIME 1140

H.O. FILE 1100-76-03

A/C TYPE ANSON II

NO. 7603

CRASH CAT. "B"

S.E. M.E. DAY NIGHT
x x

COMMAND

PERSONNEL

RANK

NUMBER

DUTY

INJURIES

SIGNAL

SCHOLEFIELD, R.J.

F/O

J14720

FI

Uninj.

NO. DATE
Lettergram

SIMS, P.M.

SGT

769

PASS

Uninj.

D 14 (REVISED)

MUIR, J.W.

LAC

R50543

PP

Uninj.

NO. CHECKED
3

MELLOR, R.P.

LAC

R254528

PP

Uninj.

#17

MONTH

FORCED LANDING

TAXYING

LANDING

TAKE-OFF

FLIGHT

STATIONARY

FATAL

INJ.

3RD INJURY

RAF

STAGE OF FLIGHT

ENGINE

ENGINE NUMBER (S)

HOURS FLOWN BY PILOTS

Jacobs L6MB

14197/25508 slight

15288/25599 "

INST.

NIGHT

ON TYPE

TOTAL

DUAL

SOLO

DUAL

SOLO

75

65

24

542

200

813

10

5

8

4

51

36

12

3

8

6

50

45

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Pilot was to leave Sgt Sims (AG)
at R.2 on completion of one hour I.F.

NATURE OF ACCIDENT: instructions.

TECHNICAL OFFICER'S REPORT:

NIL

LBG/PSW/USG/XGM

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

Instructor landed on rough area of
aerodrome between landing strip
and control tower and struck ditches
partially obscured by grass, badly
damaging a/c.

CLASSIFICATION:

7. Others.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Pending