

ACCIDENT CLASSIFICATION

UNIT 34 S.F.T.S. Medicine Hat	COM. 4	PLACE Holmsom, R.L.	DATE 9-9-44	TIME 1115
A/C TYPE M/MOTH		NO. 4940	CRASH CAT. "B"	H.Q. FILE 1100-49-40
		S.E. X	M.E.	DAY X
				NIGHT

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
OSBORNE, P.N.	A/F/L	151968	P	Uninj.	No.	DATE
BROMFIELD, G.R.	F/O	152116	PASS	Uninj.	D 14 (REVISED)	
					No.	CHECKED
					1	<input checked="" type="checkbox"/>
					#1	

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				DUAL	SOLO	DUAL	SOLO
Menasco D.4	4147/18225 Nil			31	27	127	913
				35	33	97	713

ACCIDENT CLASSIFICATION

COMMAND
MOB
FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STAY IN
FATAL
INJURY
3RD
5
M

PURPOSE OF FLIGHT:

Local flying practice.

NATURE OF ACCIDENT:

This a/c made a normal landing,
after which a violent swing to right
developed causing damage to a/c.

TECHNICAL OFFICER'S REPORT:

NIL

LS/PSS/USS

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

2. Swung.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

NIL