

## CASPIR ARCHIVAL METADATA

---

<b>Serial:</b>	8543
<b>Title:</b>	Avro Anson Mk. II serial:8543 Accident Card
<b>Author:</b>	Royal Canadian Air Force (RCAF)
<b>Subject:</b>	This accident involved 1 aircraft on 1944-October-20. Anson II s/n 8543. This accident involved 2 people. Hughes CR, Jones DIG
<b>Keywords:</b>	RCAFAnson II,8543,2 FIS,2 Flying Instructor School,Aerodrome,1944-October-20,Hughes,JonesRCAF L20
<b>Created:</b>	1944-10-20
<b>Link:</b>	<a href="https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#8543">https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#8543</a>

ACCIDENT CLASSIFICATION

UNIT <b>2 F.I.LS. Pearce, Alta.</b>	COM. <b>4</b>	PLACE <b>M.A.</b>	DATE <b>20-10-44</b>	TIME <b>1110</b>
A/C TYPE <b>ANSON II</b>		NO. <b>8543</b>	CRASH CAT. <b>"D"</b>	H.Q. FILE
		S.E.	M.E. <b>x</b>	DAY <b>x</b>
				NIGHT

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
<b>Jones, D.I.G.</b>	<b>W/C</b>	<b>G1356</b>	<b>Recat.</b>	<b>Test Uninj.</b>	No.	DATE
<b>Hughes, C.R.</b>	<b>F/L</b>	<b>J14557</b>	<b>Recat.</b>	<b>Test Uninj.</b>	D 14 (REVISED)	
					No.	CHECKED
					<b>#23</b>	

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				DUAL	SOLO	DUAL	SOLO
<b>Jacobs L6MB</b>	<b>26314/14800 N11 26523/25009 N11</b>	<b>81</b>	<b>85</b>	<b>45</b>	<b>122</b>	<b>132</b>	<b>1731</b>
		<b>105</b>	<b>214</b>	<b>90</b>	<b>1180</b>	<b>186</b>	<b>1331</b>

ACCIDENT CLASSIFICATION

COMMAND  
MONTH  
STAGE OF FLIGHT

FORCED LANDING  
TAXYING  
LANDING  
TAKE-OFF  
FLIGHT  
STAT'RY  
FATAL  
INJ.  
INJURY

RAF

PURPOSE OF FLIGHT:

Recategorization Test

NATURE OF ACCIDENT:

U/C retracted while carrying out  
precautionary landing.

TECHNICAL OFFICER'S REPORT:

Failure of Warning horn device.

LUC / PCDUW / UC DL / UDW

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

7. Others.

SECONDARY OR CONTRIBUTORY FACTORS:

32. U/C Drill - In Air.

ACTION TAKEN:

Nil.