

CASPIR Aircraft Accident Cards

Serial: 11314

Title: Avro Anson Mk. II serial:11314 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1944-October-31. Anson II s/n 11314. This accident involved 2 people. Hougan AS, Scott DH

Keywords: RCAFAnson II,11314,2 FIS,2 Flying Instructor School,Aerodrome,1944-October-31,Hougan,ScottRCAF L20

Created: 1944-10-31

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#11314>

PURPOSE OF FLIGHT:

Routine training.

NATURE OF ACCIDENT:

Engine failed just after take-off.
Successful forced landing carried
out on Aerodrome.

TECHNICAL OFFICER'S REPORT:

Cam Ring drive gear failed on stbd. engine.

SFE/ET/VA/D/S

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

15. Force Land

SECONDARY OR CONTRIBUTORY FACTORS:

27. Engine Trouble - No Damage.

ACTION TAKEN:

Nil