

ACCIDENT CLASSIFICATION


| | | | | |
|--------------------------------|-------------------|--|--------------------------|--------------------------------|
| UNIT 145 Sqdn. | COM. E. | PL. RCAF Stn. Dartmouth, NS. | DATE 3-10-44 | TIME 1222 |
| A/C TYPE VENTURA GRV | | NO. 2172 | CRASH CAT. "C" | H.Q. FILE 1100-21-72 |
| PERSONNEL | | RANK | NUMBER | DUTY |
| CLARK, G.R. | | F/O | J25257 | P. |
| ARNOLD, T.S. | | LAC | R173082 | Pass. |
| ADAMS, J.O. | | LAC | R199522 | Pass. |
| INJURIES | | SIGNAL | | |
| Uninj. | | NO. | DATE | |
| Uninj. | | A703 | 3-10 | |
| Uninj. | | D 14 (REVISED) | | |
| | | NO. | CHECKED | |
| | | | ✓ | |
| | | 1 | | |

| ENGINE | ENGINE NUMBER (S) | HOURS FLOWN BY PILOTS | | | | | |
|--------------------------|---------------------------------------|-----------------------|-------|---------|--------|--------|-------|
| Pratt & Whitney R2800-31 | P95574/114064 Nil S263461/2010 Nil | INST. | NIGHT | ON TYPE | | TOTAL | |
| | | | | DUAL | SOLO | DUAL | SOLO |
| | | 1700 | 85:00 | 15:00 | 460:00 | 170:00 | 68:00 |
| | | | | | | | |

ACCIDENT CLASSIFICATION

COMMAND
MONTH
STAGE OF FLIGHT

FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STRATRY
FATAL
INJ
INJURY



PURPOSE OF FLIGHT:

Test Aircraft.

TECHNICAL OFFICER'S REPORT:

Nil

LS/PSS/USS

NATURE OF ACCIDENT:

Landing in gusty cross wind.
Aircraft started to swing to port.
On correction tail wheel was damaged.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

2. Swung

SECONDARY OR CONTRIBUTORY FACTORS:

34. U/C Strain

ACTION-TAKEN:

Nil