

ACCIDENT CLASSIFICATION									
UNIT 9 B.G.S. Mont Joli		COM. 3	PLACE 1 mile SW of Luceville			DATE 4-10-44	TIME 1055		
A/C TYPE BATTLE			NO. 5331		CRASH CAT. "B"	H.Q. FILE 1100-53-31			
					S.E. X	M.E.	DAY X	NIGHT	
PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL		
SUTHERLAND, A.L.		P/O	J42943	P	Uninj.		NO.	DATE	
FISHER, D.M.		LAC	R281866	AG	Uninj.		N107	4-10	
GEORGE, P.D.		LAC	R272437	AG	Uninj.		D 14 (REVISED)		
							NO	CHECKED	
							1		
							#1		
ENGINE		ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS					
Merlin III		8621/31351 slight		INST.	NIGHT	ON TYPE		TOTAL	
						DUAL	SOLO	DUAL	SOLO
				42	28	4	295	144	468
ACCIDENT CLASSIFICATION									

PURPOSE OF FLIGHT:

Scheduled camera gun exercise.

TECHNICAL OFFICER'S REPORT:

FB/AOP/ES/NK/1

NATURE OF ACCIDENT:

Engine failure in air cause obscure
Pilot was getting no effect from
use of throttle. Engine r.p.m.
dropped to 1200. Fuel supply checked
O.K.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

17. Forced landing.

SECONDARY OR CONTRIBUTORY FACTORS:

26. Engine trouble - accident.

ACTION TAKEN:

NIL