

PURPOSE OF FLIGHT:

Cross Country

TECHNICAL OFFICER'S REPORT:

Engine seizure, No. 2 Cylinder.

NATURE OF ACCIDENT:

Port engine failed approx. 2 mls.
from M.A. No. 6 S.F.T.S. Pilot carried
out successful Single Engine forced
landing on M.A., No. 6 S.F.T.S.

SFE/ET/IM/D/I

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

17. Forced Landing

SECONDARY OR CONTRIBUTORY FACTORS:

26. Engine Trouble - Accident.

ACTION TAKEN:

Nil