

ACCIDENT CLASSIFICATION

UN #2 W.S. Flying Sqdn. Shepard, Alta.	COM. 4	PLACE #2 W.S. Flying Sqdn. Shepard, Alta.	DATE 11-11-44	TIME 13.30
A/C TYPE HARVARD IIB HARVARD II		NO. FH 147-D 3833	CRASH CAT. "D" "F"	H.Q. FILE 1300-FH147
		S.E. x	M.E.	DAY x NIGHT

COMMAND

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
GARIEPY, R.V., 147	Sgt.	R198828	P	Uninj.	No.	DATE 11-44
ROWE, O.E.,	LAC	R289433	WAG U/T	Uninj.	D 14 (REVISED)	
GRESSWELL-CLOUGH, D.,	F/Sgt	R110058	P	Uninj. 3833	No.	CHECKED
BULGER, R.P.,	LAC	R288795	WAG U/T	Uninj.	1	
					13	


MONTH

STAGE OF FLIGHT

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
Wasp	42-10089/22481 Nil					DUAL	SOLO
Wasp	4191/8172 No damage	45	24	3	52	151	174
		60	24	2	500	160	940
							1100

FORCED LANDING  
TAXYING  
LANDING  
TAKE-OFF  
FLIGHT  
STATRY  
FATAL  
INJ.  
3RD  
INJURY

ACCIDENT CLASSIFICATION



PURPOSE OF FLIGHT:

W.A.G. Ex.

TECHNICAL OFFICER'S REPORT:

Nil

TCA/PCT/XGI ✓

TCA/XA

NATURE OF ACCIDENT:

Pilot of A/C Harvard FH147 taxied into Harvard A/C 3833 while latter was stationary running up on line. Pilot of A/C Harvard FH147 applied brake but due to wet snow condition of the runway- A/C Harvard FH147 crashed Harvard 3833 causing damage to stbd. main plane of Harvard FH147 and damage to wing tip and aileron of A/C Harvard 3833.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

9. Collisions.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Log Book Endorsed Carelessness.