

ACCIDENT CLASSIFICATION

UNIT 1 S.F.T.S.	COM. 1	PLACE Camp Borden, Ont.	DATE 24-12-44 TIME 0950
A/C TYPE HARVARD II HARVARD II		NO. 3312 -D 3777	H.Q. FILE 1100-37-77
		CRASH CAT. "D" "A"	S.E. X M.E. X DAY X NIGHT


PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
MULLER, J. E., 33/2	LT	N1107	FI	Uninj.	NO.	DATE
STEPHENS, F.T., AUS	LAC	438569	PP	Uninj. 3777	L/G	24-12
VOLDER, L., 33/2	LAC	N2635	PP	Uninj.	D 14 (REVISED)	
					NO.	CHECKED
					2	
					20	

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
Wasp 5341	4779/9948 Slightly	INST.	NIGHT	ON TYPE		TOTAL	
				DUAL	SOLO	DUAL	SOLO
Wasp 5341	4402/8543 Nil	26	42	35	31	102	740
		10	5	20	7	48	33
		16	4	18	7	73	54

ACCIDENT CLASSIFICATION

COMMAND
MONTH
STAGE OF FLIGHT

FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJ.
INJURY 3rd
INJURY 5th



PURPOSE OF FLIGHT:

) Training

NATURE OF ACCIDENT:

) Occupants of a/c 3312 failed to see
) a/c 3777 parked at take off position
) due to zero visibility caused by
) blowing snow. This condition was
) caused by other a/c taking off and
) running up prior to take off.

CLASSIFICATION:

) 9. Collisions.

SECONDARY OR CONTRIBUTORY FACTORS:

TECHNICAL OFFICER'S REPORT:

Nil. TCA/PCT/WVCA ✓
TCA/LA

MULT

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

ACTION TAKEN:

Pending