



PURPOSE OF FLIGHT:

Dual instruction on new type.

NATURE OF ACCIDENT:

While taxiing, a/c struck a work stand being transferred between No's 6 and 4 Hangars, damaging stbd. propeller wing, and flap.

TECHNICAL OFFICER'S REPORT:

Nil

TCO/PCT/XOM

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

9. Collisions

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN: Pilot logged.