

ACCIDENT CLASSIFICATION											
UNIT 9 B & G S Mont Joli, P.Q.,		COM. 3	PLACE 3½ mls. S.W. Station Aerodrome, St. Luce, P.Q.		DATE 11-12-44 TIME 1515		H.Q. FILE 1100-74-63		COMMAND MONTH STAGE OF FLIGHT		
A/C TYPE BATTLE			NO. 7463		CRASH CAT. "C"		S.E. X	M.E. 		DAY X	NIGHT
PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL				
BEAULIEU, J.L.R.S.		F/O	J26379	P.	Uninj.		NO. N 116	DATE 12-			
MILLER, D.,		LAC	R290609	AG/UT	Uninj.						
McQUEEN, A.R.,		LAC	K268541	AG/UT	Uninj.		D 14 (REVISED) *				
							No. 3	CHECKED			
							3				
ENGINE	ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS								
Merlin III	8448/5429 Serious		INST.	NIGHT	ON TYPE		TOTAL				
			46	67	DUAL	SOLO	DUAL	SOLO			
					4	221	155	946			
ACCIDENT CLASSIFICATION											

PURPOSE OF FLIGHT:

Scheduled Gunnery Ex.

NATURE OF ACCIDENT:

While returning from completion of gunnery ex. engine failed, r.p.m.s. dropped to idling and a/c was losing height rapidly. Pilot after opening throttle with no result, turned off gas and switches and forced landed in grass field.

CLASSIFICATION:

17. Forced Landing

SECONDARY OR CONTRIBUTORY FACTORS:

26. Engine Trouble - Accident.

R. C. A. F. L 20 (REVISED)
2M-5-44 (4638) K. P. 8688
N. O. 885-L 20

TECHNICAL OFFICER'S REPORT:

Engine failure. #3 bank.

FB/AOP/ES/VA/NK/1

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

ACTION TAKEN:

Mil