

ACCIDENT CLASSIFICATION


UNIT 4 S.F.T.S.	COM. 2	PLACE M.A.	DATE 22-1-45	TIME 2100
A/C TYPE CRANE I CRANE I			NO. 7824-D 8734	CRASH CAT. 00 00
H.Q. FILE 1160-87-34		S.E.	M.E. X	DAY
				NIGHT X

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
LANNAN, P.C.,	LAG	R224883	P.P.	Uninj.	NO. L/Gran.	DATE 23-1
ISRAEL, G.A.,	Cpl.	B75037	P.P.	Uninj.	D 14 (REVISED)	
					NO. 2	CHECKED
					9	

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS						
		INST.	NIGHT	ON TYPE		TOTAL		
				DUAL	SOLO	DUAL	SOLO	
Jacobs	S-21727/4668	Slightly						
LAMB	P-21808/4783	"						
Jacobs	S-21511/4377	N11	23	20	40	17	87	60
LAMB	P21372/4230	N11	30	14	44	20	97	64

ACCIDENT CLASSIFICATION

COMMAND
 MONTH
 STAGE OF FLIGHT
 FORCED LANDINGS
 TAXIING
 LANDING
 TAKE OFF
 FLIGHT
 STRATY
 FATAL
 INJ. 3rd
 INJURY 5th



PURPOSE OF FLIGHT:

Night Flying Circuits.

NATURE OF ACCIDENT:

While taxiing back to the take-off
post after completing a night circuit
and landing, the student in a/c 7824
failed to look around carefully. It
was a clear night, half moon shining,
and good visibility.

CLASSIFICATION:

9. Collisions

SECONDARY OR CONTRIBUTORY FACTORS:

TECHNICAL OFFICER'S REPORT:

N11

MULT
TCA/PCT

TCA/XA

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

ACTION TAKEN:

Summary