



ACCIDENT CLASSIFICATION

UN No. 6 Sqdn. Coal Harbour, BC		COM. W.	PLACE 4 mls. W. of RCAF Stn. Tofine.	DATE 9-2-45	TIME 2320
A/C TYPE CANSO "A"		NO. 11007	CRASH CAT. "A"	H.Q. FILE 1100-110-07	
		S.E.	M.E. X	DAY	NIGHT X

COMMAND

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
SCHOLES, R.J.,	F/O	J27380	P.	1P Serious	NO. 05	DATE 9-2
LAKE, L.C.,	F/O	J44502	P.	2P Slight		
KNEGTEL, E.E.	F/O	J12494	P.	Slight	D 14 (REVISED)	
CAMPBELL, J.B.,	WO2	R172119	WAG	Slight	NO. 1	CHECKED
HENNINGSEN, C.H.,	WO2	R194188	WAG	Slight		
BELL, R.F.,	Sgt.	R91816	F.E.	Slight	1	
HACKER, R.W.,	F/S	R63814	F.E.	Slight		
PIKE, B.J.,	AW1	W315904	Pass.	Slight		
SARTORIUS, C.C.	P/O	J84342	Pass.	Slight.		


MONTH

FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJURY

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				DUAL	SOLO	DUAL	SOLO
Twin Wasp	P20847/12153 Seriously	64	80	7	817	303	1386
	S20585/11541 Seriously	44	31	12	160	138	261
		106	72	10	624	158	1778

STAGE OF FLIGHT

ACCIDENT CLASSIFICATION



PURPOSE OF FLIGHT:

Returning to base from familiarization flight.

NATURE OF ACCIDENT:

Port engine failed immediately after take-off Pilot feathered propeller, but was unable to maintain climb and landed straight ahead. Weather CAVU No moon.

CLASSIFICATION:

15. Force Land

SECONDARY OR CONTRIBUTORY FACTORS:

26. Engine Trouble - Accident.

TECHNICAL OFFICER'S REPORT:

Port engine failure.

OFM/AOP/ES/NK

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

MALCOLMSON, L.H.,
HOOGE, W.A.F.
MARLETT, D...

W02
Sgt.
R50807
R98604
YMCA

Pass.
Pass.
Pass.

Slight
Slight
Slight

ACTION TAKEN:

Nil