

CASPIR ARCHIVAL METADATA

Serial:	11639
Title:	Avro Anson Mk. V / VA serial:11639 Accident Card
Author:	Royal Canadian Air Force (RCAF)
Subject:	This accident involved 1 aircraft on 1945-March-06. Anson V s/n 11639. This accident involved 6 people. Brown DT, Johnston BC, Rushton HF, Stonehouse TC, Tafuro AJ, Wilson FAWJ
Keywords:	RCAFAnson V,11639,124 Sqn,124 Ferry Squadron,Trenton Ontario,1945-March-06,Brown,Johnston,Rushton,Stonehouse,Tafuro,WilsonRCAF L20
Created:	1945-03-06
Link:	https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#11639

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62

ACCIDENT CLASSIFICATION

UNIT	124 Ferry Sqdn. COM. 1	PLACE	R.C.A F. Trenton, Ont.	DATE	6-3-45	TIME	1500
A/C TYPE		NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
ANSON V		11639	"C"		X	X	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
WILSON, F.A.W.J., CAN.	F/L	C274709	P.	Uninj.	NO.	DATE
BROWN, D.T., CAN.	F/O	J16797	Pass.	Uninj.	A.671	7-3
STONEHOUSE, T.C. CAN.	F/O	J18404	Pass.	Uninj.	D 14 (REVISED)	
JOHNSTON, B.C., CAN.	F/O	J6165	Pass.	Uninj.	NO.	CHECKED
RUSHTON, H.F., CAN.	F/O	J18892	Pass.	Uninj.	2	
TAFURO, A.J., CAN.	F/O	J22151	Pass.	Uninj.	2	

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
P. & W.	P30916B/13543	INST.	NIGHT	ON TYPE		TOTAL	
AN 14 B	S.A274709/13199			DUAL	SOLO	DUAL	SOLO
		35	25	2	40	65	950

COMMAND	MONTH	STAGE OF FLIGHT
		FORCED LANDING
		TAXIING
		LANDING
		TAKE-OFF
		FLIGHT
		STATRY
		FATAL
		INJ.
		3RD
		5

ACCIDENT CLASSIFICATION

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62

PURPOSE OF FLIGHT:

Ferrying pilots to ferry aircraft.

TECHNICAL OFFICER'S REPORT:

Nil

LS/PSS/UBF/WWC

NATURE OF ACCIDENT:

A/C swung after landing in crosswind, COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:
brakes failed damage to right propeller FINDINGS: and to tail wheel unit. SUMMARY No.

CLASSIFICATION:

2. Swung.

SECONDARY OR CONTRIBUTORY FACTORS:

36. Brake Failure.

ACTION TAKEN:

Nil