

ACCIDENT CLASSIFICATION

UNIT 7 A.O.S.		COM. 2	PLACE 7 A.O.S. Airport		DATE 13-3-45	TIME 15.05			
A/C TYPE ANSON I		NO. 6876	CRASH CAT. <del>WOG</del>		H.Q. FILE 1100-68-76	S.E.	M.E. X	DAY X	NIGHT

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
THOMPSON, B.E.,	WO2	R168267	P.	Uninj.	No.	DATE
HOLLEBON, A.B., AUS.	LAC	449574	1 Nav.	Uninj.	No. Sig.	
SMITH, R.G.,	LAC	R281915	2 Nav.	Uninj.	D 14 (REVISED)	
SCROOP, E.E., AUS.	LAC	442943	3 Nav.	Uninj.	No.	CHECKED
WHITE, A.,	Cpl.	R204677	WOG	Uninj.	4	
<del>WHITE, A.</del>					2	

ENGINE	ENGINE NUMBER	HOURS FLOWN BY PILOTS					
Cheetah IX P.A228719/AS32763 N11	INST.	NIGHT	ON TYPE		TOTAL		
			DUAL	SOLO	DUAL	SOLO	
Cheetah IX S.A133992/AS16826 N11		50	314	140	1118	172	1150

ACCIDENT CLASSIFICATION

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING

TAXIING

LANDING

TAKE-OFF

FLIGHT


STAYRY

FATAL

INJURY

3RD

5



PURPOSE OF FLIGHT:

Nav. Ex.,

NATURE OF ACCIDENT:

Stbd. engine running rough  
necessitating return to base.

TECHNICAL OFFICER'S REPORT:

No. 2 exhaust valve on stbd. engine burned.

*SFE/ET/VA/D/I*

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

17. Forced Landing.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil