

CASPIR Aircraft Accident Cards

Serial: HB268

Title: Beechcraft Expeditor Mk. II serial:HB268 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1945-March-05. Beechcraft Expeditor II s/n HB268.
This accident involved 2 people. Rice RO, Sullivan PJ

Keywords: RCAF Beechcraft Expeditor II, HB268, Sqn, 168 Transport Squadron, Pennfield Ridge New Brunswick, 1945-March-05, Rice, Sullivan RCAF L20

Created: 1945-03-05

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000565#HB268>

PURPOSE OF FLIGHT:

Flying Instruction.

NATURE OF ACCIDENT:

A/C swung to port on icy runway,
striking snowbank and damaging port
w/c and wing.

CLASSIFICATION:

2. Swung.

SECONDARY OR CONTRIBUTORY FACTORS:

TECHNICAL OFFICER'S REPORT:

Nil

LS/PSS/USP/ [REDACTED] /XGI/ [REDACTED] /WMC

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CAUSE: Icy conditions of the runway and gusty
cross wind blowing caused a/c to swing on icy patch
near completion of landing run.

RECOMMENDATIONS : Nil

CONCLUSIONS OF A.I.B. : Agree with findings.

ACTION TAKEN: