

61 60 59 58 57 56 55 54 53 52 51 50 49 48 47 46 45 44 43 42 41 40 39 38 37 36 35 34 33 32 31

ACCIDENT CLASSIFICATION

UNIT 170 Ferry Sqdn. COM. Lethbridge, Alta. 2 PLACE Lethbridge Aerodrome. DATE 14-3-45 TIME 1215 H.Q. FILE 1100-22-62

A/C TYPE VENTURA GRV NO. 2262 CRASH CAT. "C" S.E. M.E. DAY NIGHT X X

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
SIMPSON, T.W.,	P/O	J51549	P.	Uninj.	NO. A721	DATE 15-3
SEELEY, H.J.,	P/O	J48685	2 P.	Uninj.	D 14 (REVISED)	
MAGWOOD, G.W.,	LAC	R110685	O.C.	Uninj.	NO.	CHECKED
					7	

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				DUAL	SOLO	DUAL	SOLO
P. & W. R2800-31	P.5743/114737 Nil S5744/115270 Nil	35	300	2	2	150	1500

ACCIDENT CLASSIFICATION

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 RAF INJ. 3RD INJURY 5

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STRATY
FATAL
INJ. 3RD
INJURY 5

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61

PURPOSE OF FLIGHT:

Solo check out on Type.

TECHNICAL OFFICER'S REPORT:

TBG/PCT/XGS

Failure of tail wheel pivot casting.

NATURE OF ACCIDENT:

When parking a/c, tail wheel ran off the concrete parking strip and struck soft ground, breaking the tail wheel pivot casting.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

10. Bad Ground.

SECONDARY OR CONTRIBUTORY FACTORS:

38. Tail Wheel.

ACTION TAKEN:

Nil