

61 60 59 58 57 56 55 54 53 52 51 50 49 48 47 46 45 44 43 42 41 40 39 38 37 36 35 34 33 32 31

ACCIDENT CLASSIFICATION

UNIT 170 Ferry Sqdn COM.	PLACE 170 F.S., Lethbridge.	DATE 21-3-45 TIME 15.00
2		H.Q. FILE 1100-21-74
A/C TYPE VENTURA BRV	NO. 2174	CRASH CAT. "D"
	S.E.	M.E. X
	DAY	NIGHT X

COMMAND

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
HUNT, G.L.,	LAC	R173244	O.C.	Uninj.	NO. A.732	DATE 22-3
RICHARDS, L. S.,	LAC	R200228	O.C.	Uninj.		
McDONALD, W., CAN.	F/L	J12992	Pass.	Uninj.		
					D 14 (REVISED)	
					NO.	CHECKED
					10	

MONTH

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
P. & W., R2800-31	86739/116893 Slightly P6741/116874 #12	INST.	NIGHT	ON TYPE		TOTAL	
				SOLO	DUAL	SOLO	DUAL

STAGE OF FLIGHT

FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJ.
3RD
INJURY

ACCIDENT CLASSIFICATION

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 RAF W/S

PURPOSE OF FLIGHT:

Running up engines on ground.

TECHNICAL OFFICER'S REPORT:

Nil

NATURE OF ACCIDENT:

L/C's engines were being started by LAC's Hunt and Richards. Stbd. engine caught fire shortly after the engine started. The accessory section of the engine was damaged. F/L MacDonald was in the cabin of the plane during this period.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil.