

ACCIDENT CLASSIFICATION											
UNIT 1 S.F.T.S. Camp Borden, Ont.		COM. 1	PLACE Relief Aerodrome Edenvale - R.1			DATE 1-5-45	TIME 10.30		H.Q. FILE 1100-28-43		
A/C TYPE HARVARD II		NO. 2843		CRASH CAT. "D"		S.E. X	M.E.	DAY X	NIGHT		
PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL				
POWELL, F.D.,		F/O	J27290	F.I.I.	Uninj.		NO.	DATE			
CHUDZIK, B.,		F/S	R200509	P.P.	Uninj.		A.812		2-5		
							D 14 (REVISED)				
							NO.	CHECKED			
							1				
							1				
ENGINE		ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS							
Wasp S3H1		8575/4434 Nil		ON TYPE				TOTAL			
				INST.	NIGHT	DUAL	SOLO	DUAL	SOLO		
				105.	100.	150.	1100.	193.	1275.		
				47.	29.	50.	200.	135.	450.		
ACCIDENT CLASSIFICATION											

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STAT'RY
FATAL
INJ.
INJURY 3rd
INJURY 5th

TYPE OF A/C

TYPE OF UNIT

CATEGORY

RAF

PURPOSE OF FLIGHT:

Instructional

NATURE OF ACCIDENT:

Engine failed to catch when throttle was opened in pull up from practice forced landing. Pilot forced landed on Aerodrome R.L.

TECHNICAL OFFICER'S REPORT:

Engine failure in air.

IL FM/AOP/ES/NK/12 ✓

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

17. Forced Landing.

SECONDARY OR CONTRIBUTORY FACTORS:

26. Engine Trouble -Accident.

ACTION TAKEN:

Nil