

ACCIDENT CLASSIFICATION

UNIT 1 S.F.T.S.	COM. 1	PLACE M.A.	DATE 9-8-45	TIME 0330
Camp Borden			H.O. FILE 1100-30-06	
A/C TYPE HARVARD II	No. 3006	CRASH CAT. "D2"	S.E. x	M.E.
			DAY	NIGHT x


PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
Brown, R.T.	F/O	J29554	F.I.	N11	NO. A874	DATE 9-8
Suline, J.L.	Sgt	R253128	PP	N11	D 14 (REVISED)	
					NO. 2	CHECKED
					# 6	

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				DUAL	SOLO	DUAL	SOLO
Wasp 53H1	9074/4633	102	83	165	900	240	1070
		52	4	12	5	151	115

ACCIDENT CLASSIFICATION

COMMAND
MONTH
STAGE OF FLIGHT

FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STAT'RY
FATAL
INJ.
INJURY



PURPOSE OF FLIGHT:

Night Circuits and landings.

TECHNICAL OFFICER'S REPORT:

Nil

LS/PSS/1/USS ✓

NATURE OF ACCIDENT:

A/C swung violently on landing.
damaging port oleo, port wing and
wing tip. Instructor was unable to
stop swing.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

2. Swung.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil