	vard		UMBER:		8	CRAS	M:	"2 н		E NO: 1		3 <b>-3</b> 8	<del></del>
O C C U P A N									A. C.		TYPE TOTAL		YTA'
NAME		RANK	NO.	CLASS	EXTEN	r of	injuries	INST	NIGHT			DUAL	
ourdeau, C.S.		F/0 (	C1076	P	Uni	njure	20					1	ļ
ALERAN									<u> </u>	A CCTT	PAT CI	LASSIFI	T GA
an light a trace of the last state of the particular state in the particular state of the particular s		1			<u> </u>	,			<del> </del>	AVVID		IOUS	
					I	many				FAT		INJ	JUR
#*************************************												·····	
					Į DAD	A (1777)	TO PROPER	,	Ţ.	one	<u> </u>		
THIRD PAR	TIES:	None			PARI	AUHUI	TE DESCEN	1.1	171	)Ife			
	DATE	HOURS	LAST	CPTE O	PAUL	FAIII.				REPORTS			
AIRFRAME	PURCHD	SINCE		HRS.	4+++++++++++++++++++++++++++++++++++++	EXT	tent of d	AMAGE	FORM	SERIAL	NO.	DAT	ľE
7	<u> </u>	156		N.A.		1	Slight		L.3	2361		8_2_40	
larvard		110	1							-			.,,
ENGINE												~ _ 1.0	
Wasp	<u> </u>	197:40	1	N.A.		<u>į</u>	<u> </u>		L.3	. 2361	2361 8-2-40		

P 2P PP FI WO AG AO OC Pass

DUTY ON WHICH ENGAGED: Training	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:
NATURE OF ACCIDENT & STAGE OF FLIGHT:	DATE: TUC/PODUM/UCDT
Whilst taxiing on aerodrome, undercarriage	COMPOSITION:
was prematurely retracted.	N 4
After landing.	N. A.
	RECOMMENDATIONS:
	a common magazini militari constituti matematica in internativa in internativa in internativa in internativa i
PRIMARY CAUSE:	
- Control of the Cont	N. A.
Error in judgment on part of pilot, in that he, whilst aircraft was still in motion, pulled	
undercarriage retracting lever instead of lever	
to raise flaps.	ACTION TAKEN:
	(a) Disciplinary (b) Technical (c)other
	N.A
	1
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	
NIL	Recorded by Date
	Recorded by Date
	Checked by Date