

DUTY ON WHICH ENGAGED: ILCO/PEP/PEN/ARM/WVG) COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT: abreraft from Wpg. to Camp Court of Inquiry Borden of accident and stage of flight: DATE: 25-10-40 to 29-10-40 COMPOSITION: President S/L R.E. Dupont. (RAF) Pilot was 18 miles to the left Member F/L G.H.R. Phillips. of his track on the T.C.A. route, Member F/O Phillips. H.J. The pilot evidently executed a steep turn in poor visibility RECOMMENDATIONS: Pilots undertaking long flights should ) as shown by the path cut through the trees in which the A/C crashed. make careful navigational preparations to the fall extent of their knowledge obtained by PRIMARY CAUSE: Inadequate navigational their flying training. preparation as pilot claimed familiarity Aircraft be equipped with radio for pilots with route by "contact". Pilot endeavored who are to fly them over routes where this ) to maintain sight of the ground, wheh aid to mavigation may be used. flying in bad weather and poor **ACTION TAKEN:** (A) DISCIPLINARY (B) TECHNICAL (C) OTHER visibility. Radios supplied No12 T.C. 30-11-40. D.6 approved by A.M.T. 20-12-40. SECONDARY CAUSE OR CONTRIBUTING FACTORS: There was no radio in the aircraft. RECORDED BY DATE CHECKED BY