

אק		3	-
O	DUTY ON WHICH ENGAGED: Instrument and COURT OF INQUIRY, INVESTIGATING OFFICER TICO/PCL/PCN)	
)	low flying practice, dual instruction COMMANDING OFFICER'S REPORT:	3	
•	NATURE OF ACCIDENT AND STAGE OF FLIGHT: DATE: 7.12 NO.	3	
>	The aircraft on low flying manoeuvre composition:	ا الاستاد * - سر	
)	collided with cables in an area Wing Commander D. M. Gordon PAR	,	
)	which resembled the actual low area in which pilots were permitted to		
)	fly. The aircraft returned to its RECOMMENDATIONS:	7	
)	base and landed intact.	ر -	
)	PRIMARY CAUSE:	3	-
`	A mistake on the part of F/O Smyth	3	
<u> </u>	in not checking up the low flying)	
ر م	area more chosely. ACTION TAKEN:	5	
<u>)</u>	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER)	
ر			
))	
)			
)	SECONDARY CAUSE OR CONTRIBUTING FACTORS:)	
)	Heavy fall of snow rendering identification) :	
)	difficult. RECORDED BY DATE		
	A strong similarity between the two areas.) :	
)) \))))))))))))))))))	3	