

```
DUTY ON WHICH ENGAGED:
                                COURT OF INQUIRY, INVESTIGATING OFFICER TCO FRCT
                                     OR COMMANDING OFFICER'S REPORT:
Flying training -- circuits and landing
                                               Commanding Officer's Report
NATURE OF ACCIDENT AND STAGE OF FLIGHT:
                                     DATE:
                                                      12-12-40
                                     COMPOSITION:
   Hit marker in taxiing. The
   punil had landed on one wan-
                                             Group Captain F.S. McGill.
  towns and cut across to another.
 The snow was fairly thick and he
                                     RECOMMENDATIONS:
  was taxiing faster then usual to
                                               This pupil has been guilty of several
  avoid getting stuck. He failed to
                                               instances of careless flying. His flying
             see a boundary light
 PRIMARY CAUSE:
                                               training has since been discontinued.
              and struck it with nort wing
 Careless taxiing on the part of
thepilot.
                                     ACTION TAKEN:
                                       (A) DISCIPLINARY (B) TECHNICAL (C) OTHER
                                               D.14 approved by A.M.T. noting that the
                                               accident was due to careless taxiing on
                                               thepart of the pilot. 23-12-40.
SECONDARY CAUSE OR CONTRIBUTING FACTORS:
                                                                 RECORDED BY
                                                                                    DATE
                                                                 CHECKED BY
                                                                                    DATE
```