

COURT OF INQUIRY, INVESTIGATING OFFICER TOURANT PAINTENES LIDIT DUTY ON WHICH ENGAGED: OR COMMANDING OFFICER'S REPORT: Ferrying aircraft Court of Inquiry. NATURE OF ACCIDENT AND STAGE OF FLIGHT: DATE: 5-1-41 Engine failed and dense smoke and COMPOSITION: fumes following engine seizure Wing Commander W.A. Jones. President obliterated pilot's vision, and he Flying Officer D.W. Roberts. Member was forced to bail out before he Pilot Officer A.C. McClaskey. Member could execute a forced landing. He RECOMMENDATIONS: jumped from an altitude of 600 ft. Particular attention to be paid to No. 4 T.C.T.I. and was knocked out on alighting Running and Testing of Aero Engines on the ground PRIMARY CAUSE: Completion of Daily Inspection Certificate from 3 Engine failure caused by glycol leaks time Aircraft accepted by RCAF Test Flight uninto engine base followed by overheattil date of ferry flight should show whether ing of connecting rod bearings with these regulations have been complied with. resulting seizure. **ACTION TAKEN:** (A) DISCIPLINARY (B) TECHNICAL (C) OTHER AMT on 1100-17-32 dated 3-3-41 states that one of the main causes of glycol leaks in Merlin engines is due to the excessive ground idling, and that special attention should be drawn to T.C.T. 1 B.6 of 14-8-40, in this respect. SECONDARY CAUSE OR CONTRIBUTING FACTORS: RECORDED BY DATE CHECKED BY DATE