

TYPE OF A/C		CAUSES OF ACCIDENTS				ENGINE FAILURE						
UNIT		COM.		PLACE		DATE		TIME				
119(BR) Sqn. Yarmouth, N.S.		EAC		Aerodrome, Yarmouth		21-12-40						
A/C TYPE		No.		CRASH CAT.		SE	ME	DAY	NIGHT			
Bolingbroke		708		"C"				X	X			
NAME			RANK	No.	DUTY	INJURIES			SERIOUS			
Wigle, D.H.			S/L	C738	P	Uninjured			FATAL			
Holgate, J.E.			Cpl.	10167A	OC	Uninjured			INJURY			
Brockbank, R.P.			AC1	10017A	OC	Uninjured			CARD SERIAL NO.			
TYPE A/F & ENGINE		No.	EXTENT OF DAMAGE	REPORT FORM	SERIAL No.	DATE	HOURS FLOWN BY PILOTS					
Bol'broke		708					INST.	NIGHT	ON TYPE		TOTAL	LAST 6 MOS.
Mercury							DUAL	SOLO	DUAL	SOLO		
Mercury												
SIGNAL No. & DATE		UNIT No. & DATE		COM. No. & DATE		REPORT	FILE	DATE				
54		21-12-40		21-12-40								
NATURE OF ACCIDENT												

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

TUC/DGT/URF

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

Taxiing- brakes failed and undercart  
descended into ditch across end  
of No.2 runway.

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE: Failure of brakes.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Ditch at end of runway, which  
trapped undercart.

RECORDED BY

DATE

CHECKED BY

DATE