

Dual instruction	COURT OF INQUIRY, INVESTIGATING OFFICER LACTOR COMMANDING OFFICER'S REPORT:
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	Commanding Officer's Report
Africant tipped over on edge of air. drome. The pilot landed on the outer edge	•
ef the airedrome, the wheels became embedded in soft snow and the air-	Equadron Leader J.S. Houchin.
craft turned on its back.	RECOMMENDATIONS:
PRIMARY CAUSE: Landing on edge of aerodrome.	Demark the uncompacted from the compacted areas clearly.
	ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER
	Above being carried out. D.12 approved by A.M.T. 21-1-11.
SECONDARY CAUCE OF CONTRACT	
SECONDARY CAUSE OR CONTRIBUTING FACTORS: ' SEMARKATION OF COMPACTED FROM UN-	
ompacted snow was not clear from he air.	RECORDED BY DATE
·	CHECKED BY DATE