

-		
دبر		$\mathbf{C}^{1}$
9	DUTY ON WHICH ENGAGED! COURT OF INQUIRY, INVESTIGATING OFFICER TLOC/POL/PSF/L/N	THE STATE OF
Ö	Cross country flying by in- OR COMMANDING OFFICER'S REPORT:	11.2
$\mathbf{O}$	strument.  Chart of Inquiry.  DATE:	
$\mathbf{C}_{i}$	The aeroplane stalled and struck COMPOSITION: 27-3-41	
7		7
	the right at an altitude of approx- Squadron Leader R.E. Dipont. President	)
	riying Officer J.A.R. Mason, Member	5
(C)	* 66 Obtained to show why the milot ALCOMMENDATIONS:	<b>5</b>
•	was flying below regulation 2000 ft. All possible further efforts be made to impress	م. سائس
$\mathbf{O}$	PRIMARY CAUSE: Stolling on a minute time of failing of complex stolling and danger	77.
-	at 50 feet. The A/C was not auth— orders. Frequent and regular talks to pupil	)
	orized to fly below 2000 feet. pilots by their Squadron Commanders with the	<b>)</b>
O	Object of impressing them with the importance of	
)	ACTION TAKEN: flying discipline.	)   -
~	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER	ر ا
٠		)
•		) i
<b>)</b>		
)	SECONDARY CAUSE OR CONTRIBUTING FACTORS:	<i>)</i>
)		, 1
5)	RECORDED BY DATE	)
		)
)	CHECKED BY DATE	) :
<u>)</u>		<b>)</b>