

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Anson DG812 being started.

OR COMMANDING OFFICER'S REPORT:

Anson 8734 being towed.

R.170

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

Anson DG812 was being started by

COMPOSITION:

F.O. Clough when Anson 8734 ran into it while being towed by tractor to parking place. Subsequent

examination revealed that the brake cable on K8734 had broken.

RECOMMENDATIONS:

NIL.

PRIMARY CAUSE:

~~Broken brake cable in Anson 8734.~~

g. collision

(9)

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Ground crew interviewed.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Anson 8734 ran into DG812.~~

36. Brake Failure

(36)

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____