

	COURT OF INQUIRY, INVESTIGATING OFFICER
DUTY ON WHICH ENGAGED: Training.	OR COMMANDING OFFICER'S REPORT:
NATURE OF ACCIDENT AND STAGE OF FLIGHT: Starboard engine caught fire.	D.14 COMPOSITION:
	RECOMMENDATIONS:
Leaking gasket in the fuel pump mitted fuel to spray on magneto. Spark from magneto gap set fumes onfire. Pilot was not aware of fire and did not use his extinguisher.	ACTION TAKEN:
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	RECORDED BY DATE