

CASPIR Aircraft Accident Cards

Serial: 4803

Title: Fleet Finch Finch II serial:4803 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1942-November-03. Fleet Finch II s/n 4803. This accident involved 2 people. Hunter TR, Taylor DR

Keywords: RCAF Fleet Finch II,4803,2 FIS,2 Flying Instructor School,Renfrew Ontario,1942-November-03,Hunter,Taylor RCAF L20

Created: 1942-11-03

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000720#4803>

) DUTY ON WHICH ENGAGED:

) Dual aerobatics.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

) NATURE OF ACCIDENT AND STAGE OF FLIGHT:

) Forced landing due to failure of engine to pick up after slow roll.

DATE:

D-14

COMPOSITION:

) There appeared to be a shortage of fuel reaching the carburettor. Successful

) forced landing carried out and after

) an inspection by Maintenance was able RECOMMENDATIONS:

) to be flown back to base.

) PRIMARY CAUSE:

) Sticking float causing carburettor flooding.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

All pilots attention have been drawn again to the applicable order in the Pilots Order Book stating the cause of this type of engine failure and the corrective action to be taken.

) SECONDARY CAUSE OR CONTRIBUTING FACTORS:

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____