

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER
OR COMMANDING OFFICER'S REPORT:

Carrying out minor periodic check.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

D-14

COMPOSITION:

Electrician carrying out periodic check made an "up" selection of hydraulic undercarriage, and operated hand pump in order to check warning light, and horn circuit without insuring that jacks which had previously been in place were still there.

RECOMMENDATIONS:

If more jacks or wing trestles were available, permitting one outboard of engine nacelle, they would be readily visible to anyone entering the cabin of A/C.

PRIMARY CAUSE:

Failure of the electrician to obey published orders.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

14 days C.B. awarded.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Selected U/C without ensuring that the jacks were still in place and pumped the hydraulic hand pump.

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____