

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
TYPE OF A/C		PILOT		OTHERS		AIRFRAME FAILURE										ENGINE FAILURE																																																																																			
TYPE OF ENGINE		UNIT 16 S.F.T.S.		COM.		PLACE		DATE 15-2-43		TIME 0800		CAUSES OF ACCIDENTS																																																																																							
CATEGORY		Hagersville, Ont.		1		Main aerodrome.		H.Q. FILE 1100-71-83		MISCELLANEOUS																																																																																									
TYPE OF A/C		A/C TYPE Anson 11		No. 7183		CRASH CAT. C 4		SE ME DAY NIGHT		X X		CAUSES																																																																																							
TYPE OF ENGINE		NAME		RANK		No.		DUTY		INJURIES		SERIOUS		MISCELLANEOUS																																																																																					
CATEGORY		Breedon, E.A.		LAC		RAF1160657		PP. Uninj.				FATAL INJURY		MISCELLANEOUS																																																																																					
TYPE OF A/C		Whitton, E.E.		LAC		R75531		AFM. Uninj.						MISCELLANEOUS																																																																																					
TYPE OF ENGINE												CARD SERIAL NO.		MISCELLANEOUS																																																																																					
CATEGORY												K		MISCELLANEOUS																																																																																					
TYPE OF A/C		TYPE A/F & ENGINE		No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.		DATE		STAGE OF FLIGHT																																																																																					
CATEGORY		Anson		7183		Slight								STAGE OF FLIGHT																																																																																					
TYPE OF ENGINE		P17518		826886		Port propeller damaged.								STAGE OF FLIGHT																																																																																					
CATEGORY		Jacobs.												STAGE OF FLIGHT																																																																																					
TYPE OF A/C		SIGNAL No. & DATE		UNIT No. & DATE		COM. No. & DATE		REPORT		FILE		DATE		STAGE OF FLIGHT																																																																																					
CATEGORY		A 28		16-2-43										STAGE OF FLIGHT																																																																																					
TYPE OF A/C		NATURE OF ACCIDENT																																																																																																	

*Incident*

HAND.O.  
 INSTS.  
 WEATHER  
 DRKNS.  
 AL'G SURF.  
 OTHER  
 UND/TD  
 PRIMARY  
 TAXING  
 LANDING  
 TAKE-OFF  
 FLIGHT  
 STABTY  
 FATAL  
 INJ.  
 3RD.  
 INJURY

DUTY ON WHICH ENGAGED:

Changing over on ground.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Undercarriage collapsed while a/c on hangar apron due to someone's foot tripping the u/c selector.

DATE:

D-14

COMPOSITION:

RECOMMENDATIONS:

Supply of locking springs RCAF Ref.26DD/101758 have been ordered from Federal Aircraft Ltd. (See file 938DD-2-5)

PRIMARY CAUSE:

57. Miscellaneous.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Safety device for U/C selector is being developed on this station at present. Special instructions issued to aircrew and handling parties regarding care required when wearing large winter flying boots, and all concerned that severe disciplinary action will be taken in any further instances.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Lack of safety device to protect U/C selector lever.

RECORDED BY \_\_\_\_\_

DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_

DATE \_\_\_\_\_