

TYPE OF A/C		PILOT		OTHERS				AIRFRAME FAILURE				ENGINE FAILURE				CAUSES		MISCELLANEOUS	
UNIT 9 E.F.T.S.		COM.		PLACE				DATE		TIME		H.Q. FILE							
St. Catharines		1		Lot 1, Concession 9 Clinton Township				29-3-43		0915		1100-39-51							
A/C TYPE		No.		CRASH CAT.		SE		ME		DAY		NIGHT							
Tiger Moth		3951		NIL		X				X									
NAME		RANK		No.		DUTY		INJURIES		SERIOUS									
Sparling, L.C.		Lac.		R151377		PP		NIL.											
TYPE A/F & ENGINE		No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.		DATE		HOURS FLOWN BY PILOTS				CARD SERIAL N.			
Tiger Moth 3951		NIL.										INST. NIGHT		ON TYPE		TOTAL		LAST 6 MOS.	
G. Major 2420/89193		NIL.												DUAL SOLO		DUAL SOLO			
SIGNAL No. & DATE		UNIT No. & DATE		COM. No. & DATE		REPORT		FILE		DATE									
NATURE OF ACCIDENT																			

Forwarded Sparling

U

) DUTY ON WHICH ENGAGED:

) Solo practice.

COURT OF INQUIRY, INVESTIGATING OFFICER
OR COMMANDING OFFICER'S REPORT:

D-14

) NATURE OF ACCIDENT AND STAGE OF FLIGHT:

) Engine cut out on roll to left.
) Managed to restart A/C and return
) to straight and level flight when
) engine cut again. Unable to restart
) at A/C force landed.

DATE:
COMPOSITION:

RECOMMENDATIONS:

) PRIMARY CAUSE:

) 54. Engine failure in the air.
) Water in fuel.

ACTION TAKEN:
(A) DISCIPLINARY (B) TECHNICAL (C) OTHER
Nil.

) SECONDARY CAUSE OR CONTRIBUTING FACTORS:

RECORDED BY DATE

CHECKED BY DATE