

## CASPIR Aircraft Accident Cards

---

**Serial:** FP721

**Title:** Avro Anson Mk. II serial:FP721 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1943-April-26. Anson II s/n FP721. This accident involved 5 people. Addicott DG, Davies T, Evans JA, Tattershaw J, Terrell AG

**Keywords:** RAFAnson II,FP721,34 SFTS,34 Service Flying Training School,Cessford,1943-April-26,Addicott,Davies,Evans,Tattershaw,TerrellRCAF L20

**Created:** 1943-04-26

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#FP721>



DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Navigation flight.

OR COMMANDING OFFICER'S REPORT:

D-14.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

Staff pilot by day engaged on cross country exercise ran into bad weather.

COMPOSITION:

In addition he had an electrical fault,

and his fuel gauges did not indicate

the amount of fuel. He decided to

RECOMMENDATIONS:

make a precautionary landing.

PRIMARY CAUSE:

47. Weather.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

NIL

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

58. Precautionary landings.

33. Technical Defect ( Elect. Generator U/S allowing battery to go flat, thus elect. fuel gauges did not record)

RECORDED BY \_\_\_\_\_

DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_

DATE \_\_\_\_\_