

CASPIR Aircraft Accident Cards

Serial: FE826

Title: North American Harvard Mk. IIB serial:FE826 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-November-23. Harvard IIB s/n FE826. This accident involved 2 people. Bennett HJ, Rossitter A

Keywords: RAFHarvard IIB,FE826,34 SFTS,34 Service Flying Training School,Aerodrome,1943-November-23,Bennett,RossitterRCAF L20

Created: 1943-11-23

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE826>

PURPOSE OF FLIGHT:

Bow Flying Cross Country.

NATURE OF ACCIDENT:

Damage to lower portion of rudder discovered on "between-flight" inspection.

TECHNICAL OFFICER'S REPORT: - Rudder damaged by striking some object from the side, probably whilst turning when taxiing.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

57. Miscellaneous.

SECONDARY OR CONTRIBUTORY FACTORS:

59. Obscure.

ACTION TAKEN:

NIL.