

ACCIDENT CLASSIFICATION

UNIT 35 E.F.T.S.	COM. 2	PLACE 4 miles S.W. of MacGregor.	DATE 3-12-43	TIME 1335
A/C TYPE TIGER MOTH DH.82 C		No. 1120	H.O. FILE 1100-1120	
		CRASH CAT. NIL	S.E. X	M.E. X
			DAY X	NIGHT

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
Rosser, R.W.	LAC	1820365	PP	Uninj.	No.	DATE
					D 14 (REVISED)	
					No.	CHECKED
					#1	<input checked="" type="checkbox"/>
					#11	

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS						
IC	89186/332654	NIL	INST.	NIGHT	ON TYPE		TOTAL	
					SOLO	DUAL	SOLO	DUAL
			.35	NI	6	11	6	24

ACCIDENT CLASSIFICATION


COMMAND
MONTH
STAGE OF FLIGHT

FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJ.
3RD
INJURY
5

CATEGORY

TYPE OF UNIT

TYPE OF A/C



PURPOSE OF FLIGHT:

Exer. 5,6,7,8,9,10,&11 Solo

TECHNICAL OFFICER'S REPORT:

NIL.

NATURE OF ACCIDENT:

Pupil Pilot became lost and made a
precautionary landing.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

51. Lost.

SECONDARY OR CONTRIBUTORY FACTORS:

58. Precautionary landing.

ACTION TAKEN:

NIL.