



PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

6-7-8-9-10-15-16-17-20

Nil.

NATURE OF ACCIDENT:

Engine caught fire when student attempted to restart after landing.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

*J. ...*

CLASSIFICATION:

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Student placed on charge-disciplinary action pending.