

DUTY ON WHICH ENGAGED: Solo Flying Practice. NATURE OF ACCIDENT AND STAGE OF FLIGHT: Ianded with undercarriage retracted.	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT: Commanding Officer's Report. DATE: 25-4-41 COMPOSITION: Flight Lieutenant (Fee C.J.)
)) PRIMARY CAUSE: Inexperience on the part of the pilot, when carburettor became iced up.)	More emphasis by both G.I.S. and flying instructors on the correct use of carburettor heat. ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER
) SECONDARY CAUSE OR CONTRIBUTING FACTORS: Pilot became excited and forgot to lower undercarriage.))))))))))))))))))	RECORDED BY DATE CHECKED BY DATE CHECKED BY DATE DATE