

	DUTY ON WHICH ENGAGED: Ferrying Medical Officer to Alliston Aerodrome. NATURE OF ACCIDENT AND STAGE OF FLIGHT: At the time the pilot took off, personnel weree laying out the path for might flying. The pilot took off well to the right of the flare path, but during the take-off swung towards it sufficient to strike the taxiing post with his PRIMARY CAUSE: /wing. The taxiing pest had not as yet been lighted. Primary Cause: Pibot permitted Aircraft to swing during the take off. This was due to the inexperience on the part of the pilot.	the Pilot, in that he permitted the air-	
)	SECONDARY CAUSE OR CONTRIBUTING FACTORS:)
) う	The taxiing post had not been light the pilot failed to see it, and consequently took no avoiding action	RECORDED BY)