

	DUTY ON WHICH ENGAGED: Flying training. NATURE OF ACCIDENT AND STAGE OF FLIGHT: The aircraft lest height and commenced low flying. The aircraft crashed into a cable stretched across the Bow River at a height of 25 to	COURT OF COMPOS	DF INQUIRY, INVESTIGATING OFFICER MANDING OFFICER'S REPORT: Court of Inquiry. 20-2-41 Squadron Leader R.C. Mair, President. Flying Officer D.A.S. Laing, Member. Flying Officer R.L. Denison, Member. ENDATIONS:
	50 feet. The machine struck the water and carried on to the river PRINCE PRINCE bank a distance of about a hundred yards. The craft was completely wrecked and both occupants were immediately killed. Primary Cause: The pilot was doing unauthorized low flying.	t ACTION 1	Enlarged photographs of this and other accidents be placed in the pilot's room together with a statement of injurieds suffered by the pilots and the cause of the accidents. TAKEN: ISCIPLINARY (B) TECHNICAL (C) OTHER A.M.T. 1700-6200 22-3-41 states that Air
, , , , , , , , , , , , , , , , , , ,	SECONDARY CAUSE OR CONTRIBUTING FACTORS:		Force posters are issued to all schools for the purpose of bringing home to pilots the results of infractions of air ragulations, and enlarged photographs are not necessary. Approved 22-3-41.
)		<u>)</u>)))))))))))))))))))