

1	
)	DUTY ON WHICH ENGAGED: Solo paractice. COURT OF INQUIRY, INVESTIGATING OFFICER
)	OR COMMANDING OFFICER'S REPORT: Commanding Officers Report.
)	NATURE OF ACCIDENT AND STAGE OF FLIGHT: DATE: 5-3-41
)	Both engines quit in air. COMPOSITION:
)	After onehours flying the engines became rough. The port engine failed Wing Commander. (W.W. Brown.)
)	whilst pilot was determining on which
)	runway to make a landing, soon after RECOMMENDATIONS:
)	the starboard engine failed, resulting in a forced landing. Return of aircraft to aerodrome as soon
)	PRIMARY CAUSE: as faulty engine performance is noticed.
5	Execution of forced landing
· · ·	in heavy snow after failure of engines.
<u> </u>	ACTION TAKEN:
))	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER
)	\mathcal{O}
.) -\	
ر ،	SECONDARY CAUSE OR CONTRIBUTING FACTORS: Pilot continuing to fly aircraft for
<i>)</i>	one hour after engines became rough. RECORDED BY DATE
')	
)	CHECKED BY DATE .)
)	1)))))))))))))))))))))))))))))