

\$	<b>)                                    </b>	
) )	DUTY ON WHICH ENGAGED: PRACTICING FORCED LANDINGS.	OR COMMANDING OFFICER'S REPORT: /L FM FT OF PE DE ESPAN
) ) )	NATURE OF ACCIDENT AND STAGE OF FLIGHT: THE STUDENT PILOT DID NOT KEEP THE ENGINE WARM ON THE GLIDE DOWN, CONSEQUENTLY WHEN AN ATTEMPT WAS MADE TO START THE MOTOR IT DID NOT CATCH AN A FORCED LANDING	COMMANDING OFFICER'S REPORT.  DATE: 20-2-41  COMPOSITION: FLYING OFFICER R.S. FRASER.
)	WAS NECESSARY. THIS RESULTED IN SOME DAMAGE TO THE AIRCRAFT.  PRIMARY CAUSE:  FAILURE ON THE PART OF THE PUPIL TO	RECOMMENDATIONS: STUDENT BILOTS ARE TO BE GIVEN SPECIAL LECTURES IN REGARD TO CARBURETTOR HEAT CONTROL (GROUND SCHOOL), AND STANDING ORDERS TO THIS EFFECT HAVE BEEN ISSUED AT THIS SCHOOL.
)	KEEP ENGINE HORM, POSSIBLY DUE TO INEXPERIENCE BUT CONSIDERED DUE TO THE INADEQUATE INSTRUCTION OF CORRECT PROCEDURE.	ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER SCHOOL WRITTEN RE PROCEDURE MENTIONED IN PRIMARY CAUSE OF ACCIDENT.
)	SECONDARY CAUSE OR CONTRIBUTING FACTORS:	
) )		RECORDED BY DATE
)	<u>, , , , , , , , , , , , , , , , , , , </u>	CHECKED BY DATE