



DUTY ON WHICH ENGAGED: Flying training  
Instruction in instrument flying  
and single engine flying and landings

COURT OF INQUIRY, INVESTIGATING OFFICER  
OR COMMANDING OFFICER'S REPORT:

Commanding Officers Report.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

7-3-41

Landed with undercarriage  
retracted. The Instructor failed  
to ensure that the undercarriage  
was in the down position and landed  
with his wheels retracted.

COMPOSITION:

LVC/PCDUF/UCDL

Flight Lieutenant (R.F. Gross)

RECOMMENDATIONS:

1. Disciplinary action (This instructor to be required to remain in camp for seven days and give Link Trainer Instruction in the evening.)
2. Endorsement of Log Book.

PRIMARY CAUSE:

The instructor failed to carry  
out the proper cockpit check  
prior to landing and as a result  
failed to lower the u/c.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

The a/c landed with the u/c  
retracted.

RECORDED BY

DATE

CHECKED BY

DATE