

DUTY ON WHICH ENGAGED: Practicing
precautionary landings.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Aircraft stalled and struck ground
resulting in severe damage to the
aircraft.

PRIMARY CAUSE:

Temporary engine failure.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Wing drooping and touching the
ground.

COURT OF INQUIRY, INVESTIGATING OFFICER ^{Doc} EL OC/ADP/TCDB/ES/MC/PH
OR COMMANDING OFFICER'S REPORT:

Commanding Officers Report. IL

DATE: 7-3-41

COMPOSITION:

Group Captain (F.S. McGill.)

RECOMMENDATIONS:

That the complete close of the throttle
at the end of the sequence be omitted.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

10622

RECORDED BY

DATE

CHECKED BY

DATE