

DUTY ON WHICH ENGAGED:

Practicing climbing and
medium turns.
NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Swung off runway on landing.

COURT OF INQUIRY, INVESTIGATING OFFICER LS/PSS

OR COMMANDING OFFICER'S REPORT:

DATE: Commanding Officers Report.
12-3-41

COMPOSITION:
Group Captain (T.A. Lawrence.)

RECOMMENDATIONS:

None - other than to limit the flying training
at Mountain View to dual only, until the
runway condition improves.
C.F.S. instruction in this connection already
issued.

PRIMARY CAUSE:

Incorrect manipulation of rudder and
brake controls, after landing,
causing the aircraft to swing off
the runway.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

The aircraft, after landing, ran off
the runway and into a snow bank
on the side of the runway.

RECORDED BY _____ DATE _____

CHECKED BY _____ DATE _____