

32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1		
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32		
PILOT		OTHERS		AIRFRAME FAILURE										ENGINE FAILURE																			
CAUSES OF ACCIDENTS																																	
UNIT # 1 S.F.T.S.		COM.		PLACE										DATE 10-3-41		TIME 1715																	
Camp Borden, Ont.		1		Owen Sound, Ontario.										H.Q. FILE 1100-26-12																			
A/C TYPE		No.		CRASH CAT.		SE		ME		DAY		NIGHT																					
Harvard		2612		C.14		x				x																							
NAME			RANK	No.	DUTY	INJURIES					SERIOUS																						
Manning, C.F.R.			IAC	400230	P.	Uninjured					FATAL	INJURY																					
													CARD SERIAL NO.																				
TYPE A/F & ENGINE	No.	EXTENT OF DAMAGE	REPORT FORM	SERIAL No.	DATE	INST.	NIGHT	ON TYPE		TOTAL		LAST 6 MOS.																					
Harvard	2612	Serious	D14		24-3-41																												
Wasp S3H	8054/4137	Serious																															
SIGNAL No. & DATE		UNIT No. & DATE		COM. No. & DATE		REPORT		FILE		DATE																							
348		o 279 10-3-41																															
NATURE OF ACCIDENT																																	

TYPE OF A/C

TYPE OF ENGINE

CATEGORY

CAUSES

STAGE OF FLIGHT

UNDTD
 PRIMARY
 HAND.O.
 INSTS.
 WEATHER
 DRKNS.
 ALG SURF.
 OTHER
 UNDTD
 PRIMARY
 TAXIING
 LANDING
 TAKE-OFF
 FLIGHT
 STATRY
 FATAL
 INJ.
 INJURY 360.

DUTY ON WHICH ENGAGED:

Cross country solo.

COURT OF INQUIRY, INVESTIGATING OFFICER *FB/ADP/PCN/ET/PS/PM/E*
OR COMMANDING OFFICER'S REPORT:

DATE:

Commanding Officers Report.
24-3-41

COMPOSITION:

Wing Commander (W.E. Kennedy)

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Lost. Precautionary forced landing due to shortage of gas, with wheels down in deep snow. Aircraft overturned.

RECOMMENDATIONS:

PRIMARY CAUSE:

Pupil became lost on a cross country flight.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Pupil failed to see hydro wires and flew through them on his precautionary landing approach which upset his judgment and the a/c turned over on landing in deep snow.

30141

RECORDED BY _____ DATE _____

CHECKED BY _____ DATE _____